

Date: 10/31/13

**BHCD CODES AND STANDARDS COMMITTEE
2012 CODE CHANGE CYCLE – BOOK 7 SUMMARY
October 28, 2013**

TAB 1 - Consensus USBC Code Changes (voted as a block as shown below)

<u>Proposal</u>	<u>Description of Change</u>	<u>Page No.</u>	<u>Committee Action</u>
USBC 103.10	New item 7	1	Disapproved
USBC 103.10	Use of certain provisions or referenced codes	5	Approved as submitted
IBC 408.2	Short term holding areas	6	Approved as submitted
415.1.1 and 414.6.2	UST removal	10	Approved as submitted
USBC VCC IBC 903.2.6	Exception 5 – exercise yards	12	Approved as submitted
USBC IRC R602.10 and 602.12	Coordination practical wall bracing	14	Approved as submitted
USBC IRC R602.12.1 (3)	Fasteners for gypsum wall bracing spacing	18	Disapproved
USBC IRC R602.12.2	Clarifies language with gypsum on both sides	19	Disapproved
USBC IRC Table R602.12.4	Clarifies foot notes on wall bracing lengths (two proposals)	20	Approved as amended (<i>amended change is on page 21</i>)
USBC IECC R405.5.2	Glazing code change – consensus for interior shade factor only	22	Approved as amended (<i>interior shade portion of change only</i>)
USBC IECC R403.6	Energy efficiency of appliances – new text and exception	25	Approved as submitted
USBC IRC M1401.3	Energy efficiency of appliances - new text and exception	27	Approved as submitted
USBC VPC 608.16.10	Coffee machines	29	Approved as submitted
USBC IBC 1403.8	Air barriers	35	Approved as submitted
USBC IRC R311.2.1	Interior passage	37	Approved as submitted
USBC IRC R403.1	Depth of footings for ramps	38	Approved as submitted
USBC IRC R507	Decks	39	Approved as submitted
USBC IRC M1501.2	Transfer air	44	Approved as submitted
VCC 425.2	Site work for manufactured homes	45	Approved as submitted
13VAC5-95-20 (MHSR)	Site prep., utility connection and skirting	46	Approved as submitted
USBC/SFPC 2306.7.1	E85 Standard	47	Approved as submitted
USBC/VADR	Generator fees – (C. Littlefield)	49	Approved as submitted
USBC VCC Table 307.1	Fireworks amounts (FSBCC)	53	Approved as submitted

Date: 10/31/13

Items pulled for individual consideration and voting

<u>Proposal</u>	<u>Description of Change</u>	<u>Page No.</u>	<u>Committee Action</u>
USB 1106.3	Outpatient parking	13	Disapproved
USBC IBC 908.7	CO alarms – educational – Henrico	30	Approved as amended (<i>deleting retrofit</i>)
USBC IBC 1008.1.9.7	Delayed egress locks	33	Carry over to December 16, 2013
IBC 308	Number of residents needing assistance	51	Approved as submitted

TAB 2 - Non-Consensus USBC Code Changes

<u>Proposal</u>	<u>Description of Change</u>	<u>Page No.</u>	<u>Committee Action</u>
108.1 and 3411.9.5 (IEBC 410.1)	Accessible parking (restriping) (HJR648)	1	Disapproved
108.1 and 3411.9.5 (IEBC 410.1, 410.8.15, 705.1)	Accessible parking (restriping) (VBCOA Administrative Committee)	3	Disapproved
USBC Section 202 (903.2.1.2)	Definition of nightclub	5	Carry over to December 16, 2013
USBC VCC Table 307.1	Fireworks amounts (DHCD)	7	Approved as submitted
USBC VCC IBC 404.5	Smoke control clarification	8	Disapproved
USBC VCC IBC 404.6	Atrium sprinklers exceptions – Exception 1	9	Disapproved
USBC VCC IBC 404.6	Atrium sprinklers exceptions – Exception 3	10	Disapproved
IBC 428	Laboratories (includes SFPC proposal and new change in supplemental handout)	11	Carry over to 2015 code change cycle
USBC VCC IBC 1604	Adult education facilities	27	Disapproved
USBC IBC 1705.16, 16.1 and 16.2	Third party risk category III (new change in supplemental handout)	29	Carry over to December 16, 2013
USBC IECC R402.1.1	Wall insulation R18 or R15+3 (VBCOA)	30	Disapproved
USBC IECC R402.1.1	Wall insulation R18 or R15+3 (RECA)	34	Disapproved
USBC IECC R402.1.1	Ceiling insulation R49	37	Disapproved
USBC IECC R402.4.1.2.1	Testing ducts and exterior barriers	38	Disapproved
USBC IECC R402.3.6	Replacement fenestration	40	Disapproved
USBC IECC R403.4.2	R-3 hot water piping insulation	42	Disapproved
USBC IECC R404.1	Reinstates 75% for high efficacy lamps/luminaries	44	Disapproved
USBC IECC R405.5.2	Glazing code change – glazing area only	45	Disapproved
SFPC/VCC IBC/IFC 906.1	Delete USBC amendments for 2012 IBC/IFC	48	Disapproved

Date: 10/31/13

<u>Proposal</u>	<u>Description of Change</u>	<u>Page No.</u>	<u>Committee Action</u>
SFPC/VCC IBC/IFC 906	Delete from IBC and retain in SFPC/IFC	51	Disapproved
IBC 1008.1.9.8	Sensor lock	52	Carry over to December 16, 2013
USBC IRC R806	Attic ventilation	58	Disapproved
USBC IRC M1503.4	Make-up air	59	Approved as submitted
USBC IRC G2411.1	CSST	61	Carry over to 2015 code change cycle
USBC IPC 607.2	Hot water pipe insulation	71	Withdrawn by proponent
IWUIC	Urban interface code	72	Disapproved
VCC, IRC E3902.2	Garage GFCI	73	Carry over to December 16, 2013
VCC IRC	Habitable attic	74	Carry over to December 16, 2013